TRAWLER STERN RAMP DECK REPAIR

Repair of Vessel Stern Ramp Deck Surface

Industry:	Marine
Application:	Stern Ramp Deck Repair
Products:	Belzona 4911, Belzona 4111
Customer Location:	WA, Australia
Application Date:	2000 and 2020

PROBLEM

The area adjacent to the stern ramp of a trawling vessel is a high-traffic zone, subjected to constant crew movement and heavy, catch-laden nets dragged across the deck.

In 2000 the engineer in charge applied a Belzona 4000 product to provide a durable, non-slip surface. Twenty years later, only localised areas required attention, which were repaired using **Belzona 4111 (Magma-Quartz).**

Fishing trawler *Advancer* repaired with Belzona

Stern ramp deck pre-repair. Inset: 20-year-old Belzona 4000

Deck repairs completed with Belzona 4111

APPLICATION

The localised areas were mechanically abraded and repaired with Belzona 4111 (Magma-Quartz) to deliver high mechanical and impact strength along with excellent long-term abrasion resistance.

OUTCOME

The same engineer applied both Belzona products twenty years apart, clearly demonstrating the durability and robustness of the original application and making it an easy choice to use Belzona again for the localised repairs.

REZITECH SERVICES PTY LTD

Head Office & Hallam Workshop
109-111 Wedgewood Road
Hallam, Victoria 3803

p +61 3 8720 8600
e info@rezitech.com.au
www.rezitech.com.au

Townsville Office and Workshop
35 Innovation Ave
Bohle, QLD 4818

p +61 3 8720 8600
e townsville@rezitech.com.au
www.linkedin.com/company/rezitech-services-pty-ltd

© Rezitech Services Pty Ltd